	Page 1
JSC SPORTINE AVIACIJA Bulletin No. 012.5.Re.001A	Total 1

Bulletin No. 012.5.Re.001A

SERVICE OF THE LAK-12 SAILPLANE AFTER 500 FLIGHT HOURS OR 5-YEAR OPERATION

JSC SPORTINE AVIACIJA	Page 2
Bulletin No. 012.5.Re.001A	Total 2

1995

SERVICE AFTER 500 FLIGHT HOURS OR 5-YEAR OPERATION

The bulletin is for the LAK-12 sailplanes with the period of operation of 5 years and flight time of 500 hours.


It is required to accomplish service work after the 5-year operation or 500 flight hours.

The service work is carried out by the technical personnel having the experience in the field of maintenance and repairing plastic sailplanes.

COMPLETE THE FOLLOWING ACTION:

1. Measure backlashes of control surfaces by rear edges (when the control stick is fixed)

Measurement Chart.




Table

No.	Control surfaces	Tolerable deviations
1.	Elevators	D =±1mm
2.	Ailerons	D =±1.75mm
3.	Flaps	D =±1.5mm

à) Elevator backlash elimination:

Elevator backlash is eliminated replacing pins LAK-12 34010113. After pins replacement "scissors" between rear edges of the elevator are permitted up to **D** 2mm (see drafts No.1, No.2)

JSC SPORTINE AVIACIJA	Page 3
Bulletin No. 012.5.Re.001A	Total 3




1. Rounded rod $\frac{10 \text{ FOCT2590-71}}{\frac{10 \text{ YELA FINITAGA 2-71}}{2 \text{ Normal processing}}}$ 2. Thermal processing $\mathbf{\sigma}_{b} = 110 \pm 10 \text{kGmm}^{2}$

No.2 D=Ø6.2 H7/h6

3 Control group OST100021-72 5.Not indicated limit deviations of dimentions

Repairing dimension No.1 D=Ø6.1 H7/h6




"Scissors" between elevators are eliminated using pin of special form (see draft No.2 version "scissors")

JSC SPORTINE AVIACIJA	Page 4
Bulletin No. 012.5.Re.001A	Total 4


b) Ailerons backlash elimination:

Backlash in the aileron control attachment point is eliminated replacing spigots LAK-10A20500501 and fastening nuts 3373A-5 on the bracket of ailerons control attachment point.




Spigot LAK-10A20500501 1. Material

Draft No.4




c) Flaps backlash elimination:

JSC SPORTINE AVIACIJA	Page 5
Bulletin No. 012.5.Re.001A	Total 5



DRAFT No.6

3CKM3 Nr.6



1. Rounded rod

2. Thermal processing: $\mathbf{S}_b=120\pm10 \text{ kG/mm}^2$

JSC SPORTINE AVIACIJA	Page 6
Bulletin No. 012.5.Re.001A	Total 6


2. Measure the backlash of control stick.

Backlash of control stick is measured when the ailerons and elevators are fixed.

Tolerances of backlash:


- a) when the elevator is fixed- **D**=±1.5mm.
- b) when the ailerons are fixed- **D**=±1.5mm.

Measurement Chart




3. Measure a backlash between fuselage and wing cantilevers: Backlash is measured in the attachment point of fuselage and wing cantilevers.

Backlash tolerance- **D**=0.5mm Backlash is eliminated putting in spigots (see draft No.8)



JSC SPORTINE AVIACIJA	Page 7
Bulletin No. 012.5.Re.001A	Total 7

Draft No.8



1. Material:

- 2. Coating: C6
- 3. Not indicated limit deviations of

dimensions: Holes H14,


Shafts h14

The rest ±IT14/2

SPIGOT:

Fuselage lateral pin removing draft;

Draft No. Little load




Fuselage lateral pin is removed by gentle blows of a little load against the support plate (see draft No.9)

ATTENTION: After pin removement check the hole internal surface A. If the areas of corrosion found, grind the surface and prime.


4. Measure the transverse backlash of the stabilizer in respect to the fuselage. Backlash tolerance **D**=4mm.

Stabilizer backlash is eliminated covering the stabilizer tube surface A with additional chrome layer (see draft No.11)

JSC SPORTINE AVIACIJA	Page 8
Bulletin No. 012.5.Re.001A	Total 8



Areas of corrosion in zone A are not tolerable. If corrosion is found replace the tube LAK-12 34010300M



5. Check the state of surfaces of all sailplane units:

If there are any cracks on the varnish-paint coat, grind the surface and check if there are no cracks on the surface of unit coverings.

6. Check the glue seam of the wing tip.

Use four-times magnifying lens. No cracks in the glue seam are tolerable.

JSC SPORTINE AVIACIJA	Page 9
Bulletin No. 012.5.Re.001A	Total 9

7. Check the internal stabilizer ribs.

No cracks on the ribs surfaces are tolerable.

8. Check flaps and ailerons attachment brackets.

Lubricate axles. Replace worn pins.

- 9. Check board ribs of the wing cantilevers. No ribs damage or coming off the wing envelope is tolerable. No cracks on the external rings of brackets in the lateral attachment points of the wing cantilevers are tolerable.
- 10. Check the state of the cock and tubes in the water-ballast system. If the friction is great, disassemble and lubricate the cock. No cracks on tubes are tolerable.
 - 11. Check the rods connection tips.

Press and release fixing device. It should return to the primary position.

12. Check the security of control rods.

No backlash of locking nuts is tolerable.

13. Check the metal surfaces of control rods.

If the areas of corrosion are found, grind them with fine glass-paper and prime.

14. Check the surfaces of tubes in the fuselage truss.

If the areas of corrosion are found, grind them with fine glass-paper and prime.

15. Check gear control system.

Detach wing cantilevers from the fuselage and put the aft part of the fuselage on a trestle. Clean gear control system from dirt and lubricate.

16. Check the release hook control system.

Clean the release hook from dirt and lubricate.

ATTENTION:

Any repair of metal attachment points and parts are only permitted after concordance with the factory.