


JSC "SPORTINĖ AVIACIJA"	Page 1
Service Bulletin No. 012.9.Re.003A	Pages 3

JSC "Sportinė aviacija"
General Director



V. Ramonas
04 03



Service Bulletin No. 012.9.Re.003A

Gliders LAK-12 calendar service time 15 years changing to exploitation by technical conditions of sailplane

AB "Sportinė aviacija"
Design Director


K. Juočas
04 03 2009

JSC "SPORTINĖ AVIACIJA"	Page 3
Service Bulletin No. 012.9.Re.003A	Pages 3

1. Subject: Gliders LAK-12 calendar service time 15 years changing to exploitation by technical conditions of sailplane.

The copies of the service bulletin **No. 012.9.Re.003A** are sent to:

1. EASA, - 1 copy;
2. Civil Aviation Administration of the Lithuanian Republic (CAA) – 1 copy;
3. Aviation authorities of countries, which issued Type Certificates for the LAK-12, -1 copy;
4. For the known owners of the LAK-12 or administration of organizations (clubs) having LAK-12 gliders – 1 copy.

2. Affected:

Type: LAK-12

Manufacture: JSC "Sportinė Aviacija", Pociūnai, LT-59327 Prienai, Lithuania.

Serial numbers affected: this service bulletin applies for the gliders LAK-12, service time of which reached 20 years and, according to requirements for service life described in conclusions for service life of the glider, is done:

- 1) wings changed (serial numbers of the gliders Nr.601-Nr.657);
- 2) wing spar fittings changed (serial numbers of the gliders Nr.601-Nr.6137);
- 3) elevator control belcrank in a vertical fin is changed (serial numbers of the gliders Nr.601-Nr.6137);
- 4) for serial numbers of the gliders Nr.6137-6235.

Original type certificate: LAK-12 Ref TC 01/03, 07-Mar-08.

3. Reason: possibility to extend the service time after 20 years exploitation of sailplane.

4. Time of compliance: this service bulletin must be accomplished after 20 years exploitation of the sailplane and every 5 years from the date when service bulletin No. 012.5. Re002A works are completed.

5. Actions: after the works described in the service bulletin No. 012.5. Re002A are accomplished, service time for the glider LAK-12 is extended by 5 years from the date when service bulletin works are completed.

6. Mass and balance: the described actions affect C.G. and mass of the glider so small, that a new weight and C.G. determination is not necessary.

7. Documentation and materials:

Service bulletin No. 012.5. Re 001A;
Service bulletin No. 012.5. Re 002A.

8. Accomplishment and log entry:

Works according the service bulletin No.012.9.Re003A should be done by national CAA licensed specialists. After completion of the works described in bulletin No.012.9.Re 003A, in a logbook of the glider LAK-12 the following entries should be made:
"Service works according to the service bulletin No. 012.9.Re 003A accomplished. The glider service time is extended by 5 years. Established glider technical service life is 3000 flight hours".