



EUROPEAN AVIATION SAFETY AGENCY

EASA

Certification Directorate

Köln, 10 January 2005
EASA D(2005)

APPROVAL FROM THE EXECUTIVE DIRECTOR

N° 2005-382

Major Change for all LAK-19 serial numbers (AB "Sportine aviacija")

Whereas the Regulation (EC) N° 1592/2002, and in particular its Article 15 empowers the Agency to proceed certification tasks,

Whereas the the LBA has been entrusted by the Executive Director to carry on the above mentioned tasks,

And

Having regard to the technical visa granted by the LBA and referenced to as "LAK-19-SB No.019.4.00.001", as described in Annex I

I hereby approve

the Issue of the new Flight Manual and Maintenance Manual, Revision No. 5 for the LAK-19 sailplane. Replacement of the Cockpit "Air speed data and Loading Placard" by a new one; Operation Instruction: Flight Manual Revision No. 5; Maintenance Manual Revision 5

Done at Köln in two copies,
For the Executive Director

A handwritten signature in black ink, reading "W. Schulze-Marmeling".

W. Schulze-Marmeling
Head of Programmes Certification