

| No | File name/ Bulletin new No* | Bulletin No (old numbering system) | Bulletin | Applicability | Date of Issue |
|----|--------------------------------|---------------------------------------|--|---|---------------|
| 1 | No.017.04.001 | No.017.4.00.002 | FM and MM revision No.5 | Model LAK-17A | 2004-10-15 |
| 2 | No.017.04.002 | No.017.4.00.003 | FM and MM Issue No.2 | Model LAK-17A | 2004-10-15 |
| 3 | No.017.05.001 | No.017A.5.41.004P | MM page 5/3 revision | Model LAK-17A | 2005-08-16 |
| 4 | No.017.05.002 | No.017A.5.52.005A | Inspection of the rudder control cable in pedals joint zone | Model LAK-17A | 2005-09-19 |
| 5 | No.017.06.001 | No.017A.6.52.006A | Additional operation limitations for the LAK-17A due to tail flutter reasons | Model LAK-17A | 2006-03-29 |
| 6 | No.017.06.002 | No.017AT.6.52.001A | Additional operation limitations for the LAK-17AT due to tail flutter reasons | Model LAK-17AT | 2006-03-29 |
| 7 | No.017.06.003 | No.017A.6.01.007 I | Modification of LAK-17A glider into LAK-17AT motor glider | Model LAK-17A | 2006-07-18 |
| 8 | No.017.07.001 | No.017AT.7.66.002A | Engine firewall installation | Model LAK-17AT | 2007-05-09 |
| 9 | No.017.07.002 | No.017A.7.58.008 I | Inspection of the tow release control system | Model LAK-17A | 2007-06-05 |
| 10 | No.017.07.003 | No.017AT.7.58.003I | Inspection of the tow release control system | Model LAK-17AT | 2007-06-05 |
| 11 | No.017.07.004 | No.017AT.8.52.004I | The friction damper installation into the rudder control system | Model LAK-17AT | 2007-12-28 |
| 12 | No.017.08.001 | No.017A.8.52.009 I | The friction damper installation into the rudder control system | Model LAK-17A | 2008-01-11 |
| 13 | No.017.08.002 | No.017A.8.77.010I | Transponder installation | Model LAK-17A | 2008-03-13 |
| 14 | No.017.08.003 | No.017AT.8.77.005I | Transponder installation | Model LAK-17AT | 2008-03-13 |
| 15 | No.017.08.004 | No.017A.8.65.012I (Rev. No.1) | The engine SOLO 2350 installation into the fuselage sailplane LAK-17A | Model LAK-17A. SN135,SN140, SN141, SN149 | 2008-03-21 |
| 16 | No.017.08.005 | No.017AT.8.65.006A | Inspection shaft and bracket 580-22 of electric actuator CARR22 from engine extraction-retraction system | Model LAK-17AT | 2008-03-21 |
| 17 | No.017.08.006 | No.017AT.8.Re.007A | Extension of the approved lifetime from 1000 flight hours to 3000 hrs for the sailplane LAK-17AT | Model LAK-17AT | 2008-03-27 |
| 18 | No.017.13.001 | No.017B/BT.13.001 | Validation modification to sailplanes LAK-17B and LAK-17BT | Models LAK-17B, LAK-17BT. Serial numbers 204, 205, 206, 207, 209, 210, 215, 217 | 2013-03-28 |
| 19 | No.017.14.001 | No.017B FES.15.001 | The sailplane LAK-17B FES preparation to comply with the applicable Type Certification Basis | Model LAK-17B FES. Serial numbers 202, 203, 208, 211, 212,213, 214, 218, 219, 220, 221, 222, 223, 224, 225, 226,227, 228. | 2014-11-17 |
| 20 | No.017.16.001 | No.017B/BT.16.002 | LAK-17B/BT/B FES flap handle (rev.1.0) | Models LAK-17B, LAK-17BT, LAK-17B FES. Serial numbers: 202 - 239 | 2016-11-30 |
| 21 | No.017.17.001 | No.17A/AT.17.001 | LAK-17A/AT Wheel brake control lever | Models LAK-17A, LAK-17AT | 2017-06-01 |
| 22 | No.017.17.002 | No.017B FES.17.001 | The flight with removed FES batteries | Model LAK-17B FES. All serial numbers | 2017-09-20 |

| | | | | | |
|----|---------------|---------------------------|--|--|------------|
| 23 | No.017.17.003 | No.017B FES.17.002 | Modification of FES Battery pack, Fire warning system and Manuals | Model LAK-17B FES. All serial numbers | 2017-12-15 |
| 24 | No.017.17.004 | No.017B FES mini.17.001 | Modification of FES Battery pack, Fire warning system and Manuals | Model LAK-17B FES mini. All serial numbers | 2017-12-21 |
| 25 | No.017.18.001 | No. 017AT.18.001 | Extension of the approved lifetime from 3000 flight hours to 6000 hrs for the sailplane LAK-17AT | Model LAK-17AT | 2018-02-28 |
| 26 | No.017.18.002 | No.017A FES.18.001 | Modification of FES Battery pack, Fire warning system and Manuals | Model LAK-17A FES | 2018-05-09 |
| 27 | No.017.21.001 | 017B FES mini.21.001-R0.2 | Modifications for airworthiness certification | Model LAK-17B FES mini. Serial numbers SN001, SN002, SN004 - SN037 | 2021-03-03 |
| 28 | No.017.22.001 | No.017A.22.001 | Modification of the sailplane LAK-17A to LAK-17A FES | Model LAK-17A FES | 2022-06-08 |
| 29 | No.017.22.002 | No.017AT.22.001 | Modification of the sailplane LAK-17AT to LAK-17A FES | Model LAK-17A FES | 2022-06-08 |
| 30 | No.017.22.003 | No.017A.22.002 | Wing-tip fixator inspection | Models LAK-17A, LAK-17AT | 2022-09-21 |
| 31 | No.017.23.001 | | Airbrake blades inspection and modification | Models LAK-17A, LAK-17AT-all serial numbers Models LAK-17B, LAK-17BT-all serial numbers Model LAK-17B FES -all serial numbers up to sn 260 Models LAK-17A mini, LAK-17B FES mini-all serial numbers up to sn 044 Model LAK-17A FES- all serial numbers Model LAK-17C FES- all serial numbers up to sn 309 | 2023-01-19 |
| 32 | No.017.23.003 | | Introduction of FES GEN4 14S 56 Ah batteries | LAK-17B FES - all serial numbers up to sn 260; LAK-17B FES mini -all serial numbers up to sn 044 | 2024-02-08 |
| 33 | | | | | |

* - File name should be used only for bulletin searches. From 2023 year the file name corresponds to the bulletin number.

